Work Orde July-11-12 8:51		124	*87124*									Page 1
Item ID: Revision ID:	D350-607-511			Accept	*N90004010					Setup Start	I M	S1*
Item Name:	Quick Release	e Basket Mounting Instal	llation							Stop	*N:	S2*
Start Date: Required Date:	7/10/12 7/10/12	Start Qty: 1.00 Req'd Qty: 1.00	*1* *1*			Cust Item Customer:						
Reference:		· ·						_	т	Run Start		
Approvals:	Process Pla	ın:	Date:	Tooling:		D	Date:		ř		*N	R1*
	QC:		Date:	SPC (Y/	N):	D	Date:			Stop	*N	R2*
Sequence ID/ Work Center II	D	Operation Description	 	Set U Run l		Tool ID	Tool#	Plan Code	Accept Qty		Reject Number	Insp. Stamp
Draw Nbr	Rev	vision Nbr	2		`	_						
D350-607-3	Α		J B		2AG							
100				0.00	15				25	1/100		
100		DOCUMENT CONTRO)L	0.00	121115					T4411	IW /c	2-11-14
DC Document Control		Memo Photocopy b	oluefile & type labels per	0.00 PPPD350-607-5	511 CHG002							
140		Pick Kit		0.00			ţ					
140 Packaging Packaging		Memo		0.00						-		12/11/13/
					15.						•	
150		QC4-100% Inspect kits	for completeness	0.00	191115							
150 QC Quality Control		Мето		0.00								

-ao.opaoo Eta	Aerospace Ltd
---------------	---------------

W/O:		WORK ORDER CHANGES									
DATE	STEP	PRO	CEDURE CH	IANGE		Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
								1			
									i		
								·			
Part No	•	PAR #:	Fault Ca	tegory:	NCR	: Yes N	lo DQA:	Date: _	7 7 74. 1		
	R	esolution:	Disposit	ion:	QA:	N/C Clo	sed:	Date: _	· · · · · · · · · · · · · · · · · · ·		
NCR:		V	VORK OR	DER NON-CONFO	RMANCE	(NCR)					
DATE	STEP	Description of NC		Corrective Action	Section B		Verification	Approval	Approval		
	0.2.	Section A	Initial: Chief Eng	Action Descript Chief Eng	ion	Sign & Date	Section C	Chief Eng	QC Inspector		
					•				,		
· · · · · · · · · · · · · · · · · · ·											
							·				
		·									
		-									

July-11-12 8:51	1:04 AM			Λ,							
Item ID: Revision ID:	D350-607-	511		Accept	*N900	040	100)* 5	Setup S		*NS1*
Item Name:	Quick Relea	se Basket Mounting Insta	llation						S	Stop	*NS2*
Start Date:	7/10/12	Start Qty: 1.00	*1*		Cust Item I	D:					
Required Date:	: 7/10/12	Req'd Qty: 1.00	*1*		Customer:						
Reference:							_	_			<u>.</u>
Approvals:	Process P	Plan:	Date:	Tooling:	D:	ate:		I		tart	*NR1*
	QC:		Date:	SPC (Y/N):	D:	ate:			2	Stop	*NR2*
Sequence ID/ Work Center I	D	Operation Description		Set Up/ Run Hours	Tool ID	Tool#	Plan Code	Accept Qty	Rejec Qty		Reject Insp. Number Stamp
*160 *160*		Packaging		0.00			((2	Izzilale
Packaging		Memo		0.00			'				
Packaging		Identify and Location:	ack for shipping as per	PPP D350-607-511	Rava						
170		QC21- Final Inspection	- Work Order Release	0.00						<i>[</i>	1.1.1.
170											111/19
QC		Memo		0.00							
Quality Control										(MF 11-16
											12-11010

Dart	Aeros	pace	Ltd
------	--------------	------	-----

W/O:	1		WORK ORDER CHANGES										
DATE	STEP	PROC	EDURE CH	IANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approvai QC Inspector				
Part No:	·	PAR #:	_ Fault Ca	tegory:	_ NCR: Yes	No DQ	A:	_ Date: _					
		esolution:											
NCR:	•	, W	ORK OR	DER NON-CONFORM	ANCE (NC	R)							
DATE	STEP	Description of NC	Initial	Corrective Action Sect Action Description	ion B Sign		cation	Approval	Approval				
		Section A	Chief Eng	Chief Eng	* Date		ion C	Chief Eng	QC Inspector				
-													
			:		·								
			.					. 4					
						:							

Picklist Print

July-11-12 8:51:03 AM

Page 1

Work Order ID:

87124

Parent Item:

D350-607-511

Parent Item Name:

Quick Release Basket Mounting Installation

Start Date: 7/10/12

Required Date: 7/10/12

Start Qty: 1.00

Required Qty: 1.00

::

IPP REV:A NEW ISSUE 10-06-28 JLM VERIFIED BY: LL

Comments:	IPP REV:A NEW			KII ILD D I .								
Component Item ID/	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty		eate Status ssued
D3910-3 SW	>	Manufactured	No			140	Each	32.0000	8	7670	~ 1B	8
/				Location		Loc Qty	L	oc Code			·	
,				st507		32						
				856	94	32			,			
D3984 SM SRubber Extrusion, Crosstu	ibe	Manufactured	No			140	f	209.4840	2	2	-p	8
				Location		Loc Qty	<u>L</u>	oc Code			0	
				ST080		209.484						
_				537	07	209.484			1 5	3707		
D4143-041 Grosstube Lug Assembly,	Sm)	Manufactured	No			140	Each	0.0000		10124	10	8
D4149-0411 Crosstube Lug Assembly,		Manufactured	No			140	Each	11.0000	8	84761	~ jB	8
SMC	ر			Location		Loc Qty	<u>L</u>	oc Code			0	
-11X				ST468		11						
_				857	49	11						sal.
ANA-HAA Sm	7	Purchased	Ño			140	Each	430.0000	16	2 800	v g	6 12/11/
				Location		Loc Qty	<u>I</u>	oc Code			V	•
				357		. 1						
				121	349	1						
				ST357		429						
				120	187	13						
					769	1						
					068	17						
				-121		4						
				122	2141	394						

Dart Aerospac	e Ltd
---------------	-------

W/O:	WORK ORDER CHANGES									
DATE	STEP	PRO	CEDURE CH	IANGE		Ву	Date	Qty	Approvai Chief Eng / Prod Mgr	Approval QC Inspector
							•			
										\$ · .
······································						<u>. </u>		1:1		
Part No:	·	PAR #:	Fault Ca	tegory:	NC	R: Yes	No DQ	A:	_ Date: _	
	R	esolution:	Disposit	ion:	QA	: N/C CI	osed:	······································	Date:	<u>:</u>
NCR:		V	VORK OR	DER NON-CONFORM	MANCE	(NCF	R)			
DATE STEP		Description of NC	* ***		ection B	C: 6	Verific	ation	Approval	Approval
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng	1	Sign 8 Date	Section	on C	Chief Eng	QC Inspector
.										
•										
(•
	:						-			

July-11-12 8:51:03 AM

Work Order ID:	87124							•	
Parent Item:	D350-607-511					Start Date:	7/10/12	Required Date: 7/10/	12
Parent Item Name:	Quick Release Basket Mounting Install	lation				Start Qty:	1.00	Required Qty: 1.00	
MS2104214	Purchased	No		140	Each	1,146.0000	16 12302(-18	M
			Location	Loc Qty		Loc Code			
Smo			ST300	1146					
			119075	116					
			121011	193					ړ
			121444	686					-40
			121652	. 151		e v			
NAS1149F0432P Washer	Purchased	No		140	Each	1,006.0000	32 122441	JP 12	111/3
			Location	Loc Qty		Loc Code		,	,
•			ST275	1006					

15

991

121350

122151

Dart Aerospace L	td
------------------	----

W/O:			V	VORK OF	RDER CHANGES	h				**
DATE	STEP	PRO	PROCEDURE CHANGE					Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				•			·			
Part No	:	PAR #:	Fault Ca	tegory:	r	ICR: Yes	No DQ	۱:	Date:	
Resolution:										
NCR:		V	VORK OR	DER NOI	N-CONFORMAN	CE (NCR	R)			
DATE	STEP	Description of NC Section A	Corrective Action Section				Verific	ation	Approval	Approval
			Initial Chief Eng	Act	ion Description Chief Eng	Sign & Date	Section	on C	Chief Eng	QC Inspector
			i 							
					<u>.</u>	}				
i										
				,						
	:									
					•					

REFERENCE ONLY



DART AEROSPACE LTD.

D350-607-3 Page 17 of 19

4.0 WEIGHT AND BALANCE

Installation	Weight	LA	TERAL	LONGITUDINAL		
		Arm	Moment	Arm	Moment	
D350-607-541	80.7 lb	± 49.1 in	± 3962 in-lb	135 in	10895 in-lb	
(Standard Basket)	36.6 kg	± 1.25 m	± 45.8 m-kg	3.43 m	125.5 m-kg	
D350-607-543	65.7 lb	± 49.1 in	± 3226 in-lb	135 in	8870 in-lb	
(Lightweight Basket)	29.8 kg	± 1.25 m	± 37.3 m-kg	3.43 m	102.2 m-kg	
D350-607-545	58.7 lb	± 49.1 in	± 2882 in-lb	135 in	7925 in-lb	
(Standard Basket)	26.2 kg	± 1.25m	± 32.8 m-kg	3.43 m	89.9 m-kg	
D350-607-547	47.7 lb	± 49.1 in	± 2342 in-lb	135 in	6440 in-lb	
(Lightweight Basket)	21.6 kg	± 1.25 m	± 27.0 m-kg	3.43 m	74.1 m-kg	
D350-607-511 (Quick Release Basket Mounting Kit)	7.2 lb 3.3 kg	± 36.9 in ± 0.94 m	± 266 in-lb ± 3.1 m-kg	135 in 3.43 m	972 in-lb 11.3 m-kg	

5.0 PARTS LIST

QTY -541	QTY -543	QTY -545	QTY -547	(CETY)	QTY -501	PART NUMBER	DESCRIPTION
X						D350-607-541	HELI-UTILITY-BASKET
	Х					D350-607-543	HELI-UTILITY-BASKET
		Х		1		D350-607-545	HELI-UTILITY-BASKET
			X			D350-607-547	HELI-UTILITY-BASKET
1	1	1	1	X		D350-607-511	QUICK RELEASE BASKET MOUNTING KIT
					Х	D350-607-501	CONVERSION KIT
1	1	1	1			D0000 0	LANYADD
	<u> </u>	<u> </u>	<u> </u>	CA=	1 4-	D2690-6	LANYARD
4	4			-24-	1	-D3910-3	X-TUBE LUG
11	1	1	1			D3912-041	EYEBOLT RECEIVER ASSY
4				_c8=	-8-	-D3984-030	RUBBER EXTRUSION, X-TUBE
1				<u> </u>		D4030-041	LONG BASKET ASSY
	1			ļ		D4030-043	LONG BASKET ASSY, LIGHTWEIGHT
		1	ļ	ļ		D4032-041	SHORT BASKET ASSY
			1			D4032-043	SHORT BASKET ASSY, LIGHTWEIGHT
1	11	11	11		11	D4085-3	PLACARD-INSTRUCTIONS
. 1					1	D4086-200	PLACARD, MAX LOAD
	1				1	D4086-215	PLACARD, MAX LOAD
		1			1	D4086-220	PLACARD, MAX LOAD
			1		1	D4086-232	PLACARD, MAX LOAD
				<u>_1</u> =	1		=FWD;X-TUBE:EUG*ASSY
				1-5	<u> </u>	-D4149-041	:AET:X-TUBE:LUG'ASSY
1	1	1	1		1	D4150-041	ATTACHMENT ARM ASSY
1	1	1	1		1	D4151-041	BASKET FWD HARDPOINT ASSY (LOWER)
1	1	11	1		1	D4151-043	BASKET FWD HARDPOINT ASSY (UPPER)
6	6	6	6		6	AN4-13A	BOLT
•		***************************************	4	=16	-16-	-AN4-14A	-BOLT-
1	1	1	1		1	AN4C15	BOLT
1	1	1	1		1	AN310C4	CASTELLATED NUT
1	1	1	1		1	MS17984-C413	QUICK RELEASE PIN
6	6	6	6	C16-	<u>-22 —</u>	-MS21042Ľ4	=NUT=(OR:MS21042-4)
1	1	1	1		1	MS24665-151	COTTER PIN
2	2	2	2		2	NAS1515H4L	WASHER
12	12	12	12	32	 44	-NAS1149F0432P	LWASHER
3	3	3	3		3	NAS1149C0463R	WASHER
			<u>`</u>	<u> </u>			***************************************

• COPYRIGHT © 2010 BY DART AEROSPACE LTD •
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Revision: A
Date: 10.06.28